

### Annex C - Proposed Carriageway Surface Treatments

ROAD NO.	ROAD NAME & LIMITS	DISTRICT	TREATMENT	AREA M2	ESTIMATE £	PRIORITY	RAISED BY	DATE	COMMENTS
D3749	Elmstead Road, all	W Byfleet	Surface dress after patching	3042		8	M	2005	JO - GS/AL Insp Jan 05 Note: heavily patched
D3643	South Road, Littlewick Rd to Heather Cl (north) and to Cheapside (south)	Horsell	Haunching, 785m north side, 470m south side			8	M	2004/5	Old rolling prog - GS/AL Insp Jan 05 Reassessed.
D3766	Eden Grove Road, Shires House spur	Byfleet	Patch and gripfibre	340		7	M	2005	GS/AL Insp Jan 05 Note: F/W also.
D3637	Arthurs Bridge Rd, Well Lane to	Horsell	Plane and resurface. Top & base repair (up	1300		7	M	2004/5	Old rolling prog - GS/AL Insp Jan 05 Reassessed.
D3639	Horsell Moor, Arthurs Brg Rd to Brewery Rd	Horsell	Shallow recycle. Re-lay kerbs. Haunch unkerbed edge	1500		7	M	2004/5	Old rolling prog - GS/AL Insp Jan 05. Reassessed
D3717	Elmbridge Lane, o/s Kingfield House	Kingfield	Plane and resurface 30x6m	180		7	M	2005	KO - GS/AL Insp Jan 05
D3680	Hurst Close	Hook Hth	Patch and microsurface. 180x6.3m	1135		7	M	2005	TM - GS/AL Insp Jan 05. Note:f/w also
D3680	Hook Heath Road, Saunders Ln end	Hook Hth	Surface dress after patching. 160x8m	1280		7	M	2004/5	Old rolling prog - GS/AL Insp Jan 05 Reassessed.
D3709	Heathside Road, White Rose Ln to Bracken Cl	Mt Hermn	Plane and resurface 30mm. 115x7m	805		7	M	2005	KO - GS/AL Insp Jan 05
D3722	Gloster Road, all	Old Wokg	Microsurface	3970		6	M	2005	GS/AL Insp Jan 05 Note: F/W also.
B382	Old Woking Road, Hacketts Lane to Lincoln Drive	Pyrford	Waiting investigation - failure of trial matl - worst sect 550x7m	3850		6	M	2005	GS/AL Insp Jan 05 Note:also need to level dips
B381	Loop Road, all	Westfield	Patch & gripfibre	2440		5	M	2005	GS/AL Insp Jan 05 Note: F/W also.

D3722	Hipley Street sub stn to end of adopted	El Old Wokg	Patch & gripfibre (L 50m)	375		5	M	2005	GS/AL Insp Jan 05 No action until new development completed	*
A245	Sheerwater Road, S of rail bridge to Old Avenue	W Byfleet	<b>HRA 90x9m and 5x10m</b>	860		5	M	2005	GS/AL Insp Jan 05	
D3729	Mayhurst Avenue, all	Maybury	Patch and microsurface. 130x5.3m	690		5	M	2004/5	Old rolling prog - GS/AL Insp Jan 05 Reassessed. Note: poor markings at j/w East Hill	
D3748	Hazel Road, inside bend & rdbt	W Byfleet	kerb or haunch. Bend 30m, rdbt 25m	25		4	M	2005	GS/AL Insp Jan 05	
D3744	Pyrford Road, Boltons Ln to Old Woking Rd	Pyrford	Surface dress after patching. L 1250m. W min 5.6m, max 11.5m	8625		4	M	2005	GS/AL Insp Jan 05	
D3615	Warwick Lane, all	St Johns	Patch and gripfibre 138x3.4m	470		4	M	2004/5	Old rolling prog - GS/AL Insp Jan 05 Reassessed. Note: remove 4 post stubs	
D7217	Beech Grove	Westfield	(Shallow recycle) Patch and gripfibre ? 63x4.5m	280		4	M	2004/5	Old rolling prog - To be reassessed	
D3698	Bonsey Lane, Westfield Rd to Hoebrook Cl	Westfield	Patch and gripfibre 320x5m	1600		3	M	2004/5	Old rolling prog - GS/AL Insp Jan 05 Reassessed. Note: several recent repairs - monitor	
D3717	Queen Elizabeth Way	Kingfield	Joint treatment 605 lin.m			3	M	2005	KO - GS/AL Insp Jan 05	
D3730	Linkway, all	Maybury	Patch and microsurface. 130x5.3m	350		3	M	2005	KO - GS/AL Insp Jan 05	Note: worst bit is 50m
D3612	Hermitage Woods Crescent	St Johns	Rout and joint seal (concrete)			2	M	2004/5	Old rolling prog - GS/AL Insp Jan 05 Reassessed.	
D3608	Northwood Road	Knaphill	Rout and joint seal (concrete)			2	M	2004/5	Old rolling prog - GS/AL Insp Jan 05 Reassessed.	
D3608	Southwood Road	Knaphill	Rout and joint seal (concrete)			2	M	2004/5	Old rolling prog - GS/AL Insp Jan 05 Reassessed.	

D3608	Springfield Close	Knaphill	Rout and joint seal (concrete)			2	M	2004/5	Old rolling prog - GS/AL Insp Jan 05 Reassessed.
D3608	Hazelwood Road	Knaphill	Rout and joint seal (concrete)			2	M	2004/5	Old rolling prog - GS/AL Insp Jan 05 Reassessed.
D3609	Greenvale Road	Knaphill	Rout and joint seal (concrete)			2	M	2004/5	Old rolling prog - GS/AL Insp Jan 05 Reassessed.
D3632	Manor Road	Horsell	Widen by half metre, one side. Re-kerb, move gullies.	108		2	M	2004	GS/AL Insp Jan 05 Proposed by A.Biddle from resident request.
D3706	Moor Lane, New Lane to Bonners Close	Westfield	(Shallow recycle)			2	M	2004/5	Old rolling prog - GS/AL Insp Jan 05 Reassessed. Note: Gang to haunch short sect nr j/w Bonners Cl
D3706	Bonners Close, o/s 10 to 12	Westfield	tba - lab to assess 20x4m section	80		2	M	2005	KO - GS/AL Insp Jan 05
D3668	Blackmore Cresc, Perrin Ct to elec sub stn	Sheerwtr	Possible crack and seat where concrete slabs failed			2	M	2005	JO - GS/AL Insp Jan 05
D3775	Godley Road, all	Byfleet	Thin surfacing delaminating from concrete road			2	M	2005	JO - GS/AL Insp Jan 05 Note: unsightly but not structurally bad. Local repair by manhole.



|