

**Fig 1 : Adams Bristow Yard:  
Unauthorised storage of inert waste and skip waste.**



Fig 2 : Unauthorised storage of both inert and skip waste.



Fig 3 : Site cleared of all inert and skip waste.



Fig 4 : Site cleared.



Fig 5 : Barnfield: Unauthorised waste deposit, transfer & disposal - 2009.



Fig 6 : Unauthorised waste deposit, transfer & disposal – 2010.



**Fig 7 : Unauthorised waste deposit, transfer & disposal – 2010.**



Fig 8 : Unauthorised waste deposit, transfer & disposal – 2010.  
Starting to reduce the ground levels around the beech tree where  
waste has been tipped





**Fig 9 : Unauthorised waste deposit, transfer & disposal – 2012.  
Skips & waste cleared, just the hardcore remaining.**



**Fig 10 : Field Common South – A total of 5 Yrs +  
from establishing the breach to remediation.**

Woodyard: timber & composting.



Scrapyard & breaking.



Fig 11 :

Landscaper contractors yard



Log storage area



Fig 12 :

Timber burning, soil & hardcore tipping area.



Clearance of this area





Fig 13 :

Area of land raising at rear of lake.



Landscape contractor's compound.



**Fig 14 : Two companies with adjacent skip yards:  
used for waste deposit, transfer & recycling.**



Page 32



Fig 15 :



Fig 16 :





Fig 17 : Ecologically beneficial woodpiles



Fig 18 :



Fig 19 : Regeneration of the area that had been landraised within the willow copse.





**Fig 20 : Hurtmore Golf Course -  
Access track: removed and restored.**



## Fig 21 : A total expenditure of £1.2M + spent on site remediation.

Large bund removed and depression reinstated



This page is intentionally left blank