

LTS ID No.	Scheme	Town Village	Location	Frequency	On Flood	Status	Safety	Property	Social	Duration	Sewerage	Community	Claims	Flood o/s	Eng Opp	Route	Standing	Total	Wetspot	Probable Cause	Quick Fix? (Y/N)	Details of Quick Fix	Quick Fix Cost Guess	Notes to be added	Comment
Wok075	Carthouse Lane	Horsell	West of j/w Littlewick Rd (50m west of Burnt Barn)	H	Y	C	2	2	4	5	0	3	0	3	5	0	1	92	35	Inadequate System					Scheme in Design
Wok043	Prey Heath Road	Mayford	Rail Bridge	H	Y	C	2	0	5	5	0	3	0	0	5	0	1	73	75	River Flood					Rail Br - ITT scheme to include drainage. Also ditching
Wok065	Blanchards Hill	Sutton Green	Whole length	H	N	C	2	0	3	5	0	3	0	3	0	0	1	63	123	Ditch					Reopen ditch by demolished property nr Gabriel Cott
Wok102	White Rose Lane	Woking		H	Y	C	1	2	3	2	0	3	0	3	0	0	1	60	141	Investigation/Unknown					flooding by Park Entry - Andy Lobban LTS
Wok047	Smarts Heath Road/Berry Lane	Fox Corner	j/w Blackhorse Road and By Crastock Farm bridge over Hoe	H	Y	C	2	0	2	4	0	3	0	0	0	4	1	58	147	River Flood					Ditching work required and Requires Investigation (AL 04-06-07)
Wok071	Morton Road	Horsell	NW of Meadway Drive	H	N	C	0	2	5	3	4	3	0	3	0	0	1	57	157	Investigation/Unknown					Near school, councillor involved (AL 04-06-07)
Wok078	Lockfld drive roundabout j/w Amstel way	Goldsworth Park		H	N	C	2	0	2	2	0	3	0	0	0	4	1	54	174	Investigation/Unknown					investigate at rdbt
Wok099	Lower Guildford Road	Knaphill		H	N	C	1	2	1	2	0	3	0	3	0	0	1	52	188	Unconnected System					Nos 52-4 New gully / mains connect
Wok079	Gorselands Close	West Byfleet		H	Y	C	0	3	2	3	0	3	0	3	0	0	1	51	194	Maintenance					Major bank clearance and continuing maintenance
Wok004	Barrs Lane	Knaphill		H	N	C	0	2	3	3	0	3	3	0	0	0	1	48	215	Adjacent Runoff					See Littlewick Rd
Wok007	Littlewick Road	Horsell		H	N	C	0	2	3	3	0	3	3	0	0	0	1	48	216	Culvert					TWU and Parley Brook affects Anchor Hill/Barrs Lane
Wok005	Robin Hood Road	Knaphill	By Toldene Close investigate	H	N	C	0	2	3	2	0	3	0	3	0	0	1	43	244	System Overwhelmed					Elizebeth Compton - Many complaints from residents
Wok082	Dodds Lane	West Byfleet		H	N	C	0	2	2	2	4	3	0	3	0	0	1	43	245	Investigation/Unknown					Unknown - Requires investigation - Andy Lobban LTS
Wok097	Hook Hill Lane	Woking		H	N	C	1	1	1	2	0	3	0	3	0	0	1	42	251	Investigation/Unknown					J/w Smarts H Rd - investigate. And top end
Wok076	Egley Road/Drakes Way	Mayford		H	Y	C	0	2	2	2	0	3	0	3	0	0	1	39	272	Inadequate System					new gully and pipe section £2k
Wok084	Boundary Rd	Maybury		H	N	C	0	2	2	2	0	3	0	3	0	0	1	39	273	Investigation/Unknown					By Castings Factory - investigate
Wok100	Boltons Lane j/w Pyrford Road	West Byfleet		H	N	C	0	2	2	2	0	3	0	3	0	0	1	39	274	Investigation/Unknown					new gully ?
Wok103	Walton Terrace	Maybury		H	N	C	0	2	2	2	0	3	0	3	0	0	1	39	275	Investigation/Unknown					Requires further investigation - Andy Lobban LTS
Wok114	Birchwood Drive	West Byfleet	carriageway between houses 5 19	L	N	C	0	2	0	2	0	3	0	3	5	0	1	36	288	Ditch					Reeve Ditch maintenance problem (Not Gullies) - LTS Engineer
Wok002	Chobham Road	Knaphill	Near Golf Club	H	N	C	0	1	3	3	0	3	0	3	0	0	1	35	293	Adjacent Runoff					j/w Barrs Lane and twrds Chobham - ditching
Wok081	Pyrford Road	Pyrford		H	N	C	0	1	3	3	0	3	0	3	0	0	1	35	294	Ditch					Ditch & pipe clearance - up to 1 mile
Wok091	Robin Hood Road (N)	St Johns		H	N	C	0	2	1	2	0	3	0	3	0	0	1	35	295	Investigation/Unknown					By no.40 - investigate
Wok096	Elm Rd	Woking		H	N	C	0	2	1	2	0	3	0	3	0	0	1	35	296	Investigation/Unknown					Flooding of "Coramondal" (House) requires investigation
Wok120	Market Square o/s Post Office	Woking	o/s Post Office	H	N	C	0	0	5	2	0	3	0	3	0	4	1	34	300	Channel gully has no outlet					To be funded by Local Committee Drainage Allocation 2007/08
Wok083	Guildford Rd (Castle Green)	Castle Green		H	N	C	1	0	1	2	0	3	0	0	0	0	1	29	315	Ditch					Ditching needed (And continues into Runnymede) Andy Lobban LTS
Wok101	Rydens Way	Old Woking		H	N	C	0	1	2	2	0	3	0	3	0	0	1	29	316	Investigation/Unknown					By no 39 - investigate
Wok034	Kingfield Road	Woking	R. Wey BrLeisure Centre	H	Y	C	0	0	4	2	0	3	0	0	0	4	1	28	317	River Flood					S of Football ground - roots and ditch to Hoe
Wok062	Blackhorse Road	Knaphill	Railway Arch	H	Y	C	0	0	3	3	0	3	0	3	0	0	1	25	333	Ditch					Ditching, and poss pipe renewal at Smarts Heath end
Wok080	Hook Heath Road	Hook Heath		H	N	C	0	1	1	2	0	3	0	3	0	0	1	25	334	Inadequate System					Additional gully and pipework £6k

LTS ID No.	Scheme	Town Village	Location	Frequency	On Flood	Status	Safety	Property	Social	Duration	Sewerage	Community	Claims	Flood o/s	Eng Opp	Route	Standing	Total	Wetspot	Probable Cause	Quick Fix? (Y/N)	Details of Quick Fix	Quick Fix Cost Guess	Notes to be added	Comment
Wok085	Cherry St	Woking		H	N	C	0	1	1	2	0	3	0	3	0	0	1	25	335	Investigation/Unknown					By CMS Carpets - Investigate
Wok098	Knightswood	Goldsworth Park		H	N	C	0	1	1	2	0	3	0	3	0	0	1	25	336	Investigation/Unknown					GWP nr Lockfld dr investigate
Wok074	Holly Bank Road	St Johns	Near Cedar Road	H	N	C	0	1	1	1	0	3	0	3	0	0	1	23	345	Inadequate System					External property flood - Elizebeth Compton
Wok010	Horsell Moor	Horsell		H	N	C	0	0	3	3	0	3	0	0	0	0	1	22	351	Damaged System					Broken gully and blockages
Wok118	Rectory Lane	Byfleet	Geoff Marlow between police Station and Marlow	L	Y	C	0	0	1	5	0	3	0	3	0	0	1	21	354	System Overwhelmed					Long time to drain away after heavy showers.
Wok105	Anchor Hill	Knaphill	Bottom of hill	L	N	C	0	0	1	2	0	3	0	3	5	0	1	20	359	System Overwhelmed					SCC Councillor Diane Smith - Surface water drains overflowing
Wok109	Heath Drive	Brookwood	No. 7	L	N	C	0	1	0	1	0	3	0	3	0	0	1	19	371	Investigation/Unknown					Unrecognised as a problem by LTS Engineer
Wok119	Church Road	Byfleet	Geoff Marlow flooding at north end	L	Y	C	0	0	1	3	0	3	0	3	0	0	1	17	379	Investigation/Unknown					Geoff Marlow - Takes a long time to drain away
Wok060	Warren Lane	Pyrford		H	N	C	0	0	1	3	0	3	0	0	0	0	1	14	395	Ditch					Ditching and grips (see also Pyrford rd)
Wok068	Whitmoor Lane	Sutton Green	Whole rd	H	N	C	0	0	1	3	0	3	0	0	0	0	1	14	396	Adjacent Runoff					Further ditching
Wok044	Saunders Lane	Mayford		H	N	C	0	0	1	2	0	3	0	0	0	0	1	12	415	Adjacent Runoff					Ditching
Wok077	Runtley Wood Lane	Sutton Green		H	Y	C	0	0	1	2	0	3	0	0	0	0	1	12	416	Ditch					ditch clearing - half mile
Wok106	Huntingdon Road	Goldsworth Park		L	N	C	0	0	1	2	0	3	0	0	0	0	1	12	417	Maintenance					Maintenance Issue - LTS Engineer
Wok107	Highclere Road	Knaphill	J/W High Street	L	N	C	0	0	1	2	0	3	0	0	0	0	1	12	418	Maintenance					Maintenance Issue - LTS Engineer
Wok113	Orchard Drive	Horsell		L	N	C	0	0	0	2	0	3	0	3	0	0	1	11	429	Investigation/Unknown					Jeff Brawn - Road floods near numbers 28, and 55 - 61
Wok111	Connaught Road	Brookwood	Opposite Station Access	L	N	C	0	0	1	1	0	3	0	0	0	0	1	10	450	Investigation/Unknown					Network Rail Responsibility
Wok116	Vale Farm Road	Woking	outside house number 103	L	N	C	0	0	0	1	0	3	0	3	0	0	1	9	467	Investigation/Unknown					Unrecognised as a problem by LTS Engineer Requires investigation
Wok112	Wheatsheaf Close	Horsell		L	N	C	0	0	0	2	0	3	0	0	0	0	1	8	481	Investigation/Unknown					Related to Ferndale Road and the Grove - LTS Engineer
Wok001	Bagshot Road	Knaphill	Junc Chobham rd	H	N	C	0	0	0	1	0	0	0	0	0	4	1	7	506	Investigation/Unknown					Investigation Required
Wok012	Shores Road	Horsell		H	N	C	0	0	0	1	0	0	0	0	0	4	1	7	507	Soakaway					Insufficient capacity of soakaways - when horsell common is saturated the SAs do not work - nothing can really be done (AL 04-06-07) Steve Truluck reported that these fill VERY quickly with pine needles (29-06-07)
Wok048	Guildford Road	Mayford	By Whitmoor	H	N	C	0	0	0	1	0	0	0	0	0	4	1	7	508	River Flood					Hoe Stream river flood by Mayfor Arms (AL 04-06-07)
Wok050	High Street Send	Send	Shackleford rdBrdmead rd	H	Y	C	0	0	0	1	0	0	0	0	0	4	1	7	509	River Flood					River flood (AL 04-06-07)
Wok063	Brookwood Lye Road	Knaphill		H	Y	C	0	0	0	1	0	0	0	0	0	4	1	7	510	Inadequate System					Culvert-insufficient capacity
Wok057	Lock Lane	Wisley	Midway	H	N	C	0	0	0	1	0	3	0	0	0	0	1	6	528	Investigation/Unknown					Edge of golf course on Woking side of bridge, run-off misses gully & flows across road.
Wok108	Chobham Road	Knaphill	Next to Garibaldi Pub	L	N	C	0	0	0	1	0	3	0	0	0	0	1	6	529	River Flood					On Flood Plain - LTS Engineer
Wok115	Chertsey Road	Woking		L	N	C	0	0	0	1	0	3	0	0	0	0	1	6	530	Investigation/Unknown					No significant flooding - LTS Engineer
Wok013	Woodham Road	Sheerwater		H	N	C	0	0	0	1	0	0	0	0	0	0	1	3	622	WC Carrier					east from 6 xroads - twu or soakaway capacity ?
Wok015	Dartnell Avenue	West Byfleet		H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	623	WC Carrier					Thames system down Parvis Rd is poor, problem at j/w TW system (AL 04-06-07)
Wok016	Godley Road	Byfleet		H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	624	River Flood					Vulnerable to river flood (AL 04-06-07)
Wok017	Mill Lane	Byfleet	East end	H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	625	River Flood					New developments being built, not sure how these will be affected by flooding (/ 04-06-07)

LTS ID No.	Scheme	Town Village	Location	Frequency	On Flood	Status	Safety	Property	Social	Duration	Sewerage	Community	Claims	Flood o/s	Eng Opp	Route	Standing	Total	Wetspot	Probable Cause	Quick Fix? (Y/N)	Details of Quick Fix	Quick Fix Cost Guess	Notes to be added	Comment
Wok018	Sanway Close	Wisley		H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	626	River Flood					Vulnerable to river flood (AL 04-06-07)
Wok019	Sanway Road	Wisley		H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	627	River Flood					Vulnerable to river flood (AL 04-06-07)
Wok031	Fullerton Road	Wisley		H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	628	River Flood					Vulnerable to river flood (AL 04-06-07)
Wok032	Fullerton Close	Byfleet		H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	629	River Flood					Vulnerable to river flood (AL 04-06-07)
Wok033	Brewery Lane	Byfleet		H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	630	River Flood					Excavation required to unblock a pipe (AL 04-06-07)
Wok035	Turnoak Avenue	Woking		H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	631	River Flood					-
Wok036	Queen Elizabeth Way	Woking	Whole rd	H	N	C	0	0	0	1	0	0	0	0	0	0	1	3	632	River Flood					-
Wok037	Chestnut Grove	Mayford		H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	633	River Flood					Will be cured by development - depends on who develops as to whos responsibility it will be (AL 04-06-07)
Wok038	Maple Grove	Mayford		H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	634	River Flood					-
Wok039	Bonsey Close	Mayford		H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	635	River Flood					Will be cured by development - depends on who develops as to whos responsibility it will be (AL 04-06-07)
Wok041	Hoebrook Close	Mayford		H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	636	River Flood					River flood (AL 04-06-07)
Wok042	Smarts Heath Road	Mayford	nr Bridge	H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	637	River Flood					Capacity of bridge too small so water backs up (AL 04-06-07)
Wok045	Saunders Lane	Mayford		H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	638	Adjacent Runoff					Ditching to be done (AL 04-06-07)
Wok049	Burdenshott Road	Jacobs Well		H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	639	Ditch					Ditching done but lots more to be done - needs money for 5 yr maintenance program (AL 04-06-07)
Wok051	Riverdale Drive	Mayford		H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	640	River Flood					
Wok052	Trentham Crescent	Mayford		H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	641	River Flood					
Wok053	Riverside Gardens	Send		H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	642	River Flood					
Wok055	The Cloisters	Send		H	N	C	0	0	0	1	0	0	0	0	0	0	1	3	643	River Flood					Vulnerable due to River flood (AL 04-06-07)
Wok056	Elveden Close	Pyrford		H	N	C	0	0	0	1	0	0	0	0	0	0	1	3	644	Adjacent Runoff					Land drainage problem - poor ditches in Burhill estate (AL 04-06-07)
Wok059	Upshot Lane	Pyrford		H	N	C	0	0	0	1	0	0	0	0	0	0	1	3	645	System Overwhelmed					On j/w Pyrford Common Road, gully by private estate telegraph pole. System works as long as one vulnerable gully by pole is kept clear (AL 04-06-07)
Wok069	Hawthorn Lane	Mayford	Junction	H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	646	River Flood					Hoe Stream river flood (AL 04-06-07)
Wok070	Westfield Avenue	Woking	North end	H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	647	River Flood					River flood from Hoe (AL 04-06-07)
Wok072	St Johns Hill Road	St Johns	N of j/w Holly Bank Rd	H	N	C	0	0	0	1	0	0	0	0	0	0	1	3	648	Inadequate System					Eng Opp when bridge is sorted, structure involved
Wok073	White Rose Lane	Woking	o/s Trevano Lodge	H	Y	C	0	0	0	1	0	0	0	0	0	0	1	3	649	Inadequate System					Carriageway floods
Wok095	Smarts Heath Road	Mayford		H	N	C				1							0	1	3	655	River Flood				Requires Investigation (AL 04-06-07)
Wok104	Chobham Road	Horsell		H	Y	C				1							1	3	656	River Flood					MOVED FROM SURREY HEATH
Wok008	Thornash Road	Horsell		L	N	D				0							0	0	721	Investigation/Unknown					Investigation Required
Wok009	Horsell Common Road	Horsell		L	N	D				0							0	0	722	Adjacent Runoff					-
Wok011	Common Close	Horsell		H	N	R				0							0	0	723	Maintenance					Private ditch blocked
Wok014	Heathside Crescent	Woking		H	N	R				0							0	0	724	Inadequate System					Fixed, gullies put in (AL 04-06-07)
Wok054	Church Street	Send		L	N	D				0							0	0	725	River Flood					-

LTS ID No.	Scheme	Town Village	Location	Frequency	On Flood	Status	Safety	Property	Social	Duration	Sewerage	Community	Claims	Flood o/s	Eng Opp	Route	Standing	Total	Wetspot	Probable Cause	Quick Fix? (Y/N)	Details of Quick Fix	Quick Fix Cost Guess	Notes to be added	Comment
Wok061	Church Hill	Pyrford		L	N	D				0							0	0	726	System Overwhelmed					New carrier went in, work done and no prob since (AL 04-06-07)
Wok110	Bagshot Road	Brookwood	Crossroads (By Canal)	L	Y	R	0	0	0	0	0	0	0	0	0	0	0	0	694	Investigation/Unknown					SCC Elizabeth Compton - House and garden flooded on north side of canal
Wok117	Viscount Gardens	Byfleet		L	Y	R	0	0	0	0	0	0	0	0	0	0	0	0	695	Investigation/Unknown					Was causing flooding in Dunfee Way

On Flood Plair
Dormant
Resolved
Scheme has been given finding to go ahead this year