




LUKEY	ROAD NO	HAZARD	SPECIES	OWNERSHIP	OWNERNOTES	NOTES	DATEFIELD	LIKELIHOOD	MITIGATION
505879	A3100	Structural defect	Sycamore	Private	die back in crown		30/11/2009	2 Possible but unlikely	Monitor
505880	A3100	Sign obstruction	Unidentified	Public			30/11/2009	4 Virtually certain	Cut back visibility splay
505885	A3100	Dead wood	Oak	Public			30/11/2009	3 Possible and probable	Remove
505886	A3100	Low Branch	Beech	Private		cut back to boundary	30/11/2009	4 Virtually certain	Remove limb
505887	A3100	Structural defect	Oak	Public	gb states tree has moved and he requested tree to be felled		30/11/2009	4 Virtually certain	Fell
505513	D4012	Structural defect	Beech	Public			17/09/2009	3 Possible and probable	Fell
505514	D4012	Other	Unidentified	Public		robina with root trip hazard. remove root and repair path	17/09/2009	3 Possible and probable	Remove
505515	D4012	Structural defect	Beech	Public		hollow at base	17/09/2009	4 Virtually certain	Fell



Likelihood Priority

- 1 Highly unlikely
- 2 Possible but unlikely
- 3 Possible and probable
- 4 Virtually certain

Example data of the 2009 Survey around London Road A3100 Guildford Risk Mitigation Report - Oct 2012

This page is intentionally left blank