

OFFICER REPORT TO LOCAL COMMITTEE (MOLE VALLEY)

A245 WOODLANDS LANE, STOKE D'ABERNON / A245 WOODLANDS ROAD, LEATHERHEAD / A245 RANDALLS ROAD, LEATHERHEAD AND C131 OAKLAWN ROAD, LEATHERHEAD

12 SEPTEMBER 2012

KEY ISSUE

To seek approval to reduce the speed limit along the A245 Woodlands Lane / A245 Woodlands Road / A245 Randalls Road and C131 Oaklawn Road from the national speed limit (60mph) to 50mph.

SUMMARY

Following complaints from local residents and with the agreement of Surrey Police, Surrey County Council's Local Highway Services Group have requested that the speed limit be reduced.

OFFICER RECOMMENDATIONS

The Local Committee (Mole Valley) is asked to:

(i) Approve, subject to statutory procedure, and in conjunction with Elmbridge's Local Committee, that the speed limit on the A245 Woodlands Lane / A245 Woodlands Road / A245 Randalls Road be reduced from the national speed limit (60mph) to 50 mph, from the junction with Cobham Road / Stoke Road to the existing 30mph termination point approximately 50 metres north of the Springfield Drive roundabout.

APPENDIX 1

- (ii) Approve, subject to statutory procedure, that the speed limit on C131 Oaklawn Road be reduced from the national speed limit (60mph) to 50 mph, over its entire length.
- (iii) Approve that consideration and resolution of any objections received be delegated to the South East Area Team Manager in consultation with the Chairman, Vice Chairman, together with Divisional Member.

1 INTRODUCTION AND BACKGROUND

- 1.1 The A245 Woodlands Lane / Woodlands Road is approximately 2.4 km in length and averages 6.2 metres in width. The section of A245 Randalls Road under consideration is approximately 900 metres long and averages 7.3 metres in width. Oaklawn Road is approximately 1.2 km and averages 6 metres in width. All are rural, two-way single carriageway roads.
- 1.2 Woodlands Lane / Woodlands Road run from the junction with Cobham Road / Stoke Road in the west, generally eastwards and then south eastwards to the junction with Oaklawn Road, where it then becomes Randalls Road. The route crosses over from the Borough of Elmbridge into the District of Mole Valley approximately 800 metres north west of the junction with Oaklawn Road.
- 1.3 There are a few farms, stables and residential properties bounding the public highway throughout Woodlands Lane / Woodlands Road. This route also accesses both the Woodlands Park Hotel and Queen Elizabeth's Training College. Randalls Road accesses a waste recycling plant, the crematorium and Springfield Lane business park. Oaklawn Road accesses Pachesham Golf Club, and Tyrwhitt House and Dorincourt care centres.
- 1.4 There is no on-street parking as all properties have provision to park off the carriageway.
- 1.5 There is no street lighting throughout A245 Woodlands Lane/ Woodlands Road or Randalls Road. Woodlands Road has a footway on the western side, from the entrance to Queen Elizabeth's Training College southwards to Randalls Road. Randalls Road has a footway on the western side. Oaklawn Road is unlit and has a footway on the eastern side from Randalls Road northwards to Dorincourt, where it switches to the western side for the remainder of its length.
- 1.6 These roads are unrestricted, and therefore, in accordance with the Highway Code, subject to a speed limit of 60mph.
- 1.7 The existing road surface, road signs and markings are generally in reasonable condition, though the signing is not comprehensive.

2 ANALYSIS

- 2.1 A study of the Personal Injury Collision (PIC) records show that in the last three years there have been seventeen PICs. 5 PICs occurred on the stretch of A245 Woodlands Lane within the Borough of Elmbridge. Of the other twelve collisions, four are concentrated at the junction with Oaklawn Road. No PICs have been recorded within Oaklawn Road.
- 2.2 The number location and severity of the collisions are as follows:

A245 Woodlands Lane within Elmbridge Borough:

Location	Number of Collisions	<u>Severity</u>
Appx. 650m east of j/w Stoke Road/ Cobha outside property known as 'Little Parks' Appx. 800m east of j/w Stoke Road/ Cobha	1	slight
outside property known as 'Pine Tre Outside Woodlands Park Hotel Just north of Queen Elizabeth's Training C	ees' 2 1	1 serious serious serious
	Total 5	

A245 Woodlands Road within Mole Valley District:

Location	Number of Collisions	<u>Severity</u>
Outside Queen Elizabeth's Training Collegust south of M25 overbridge Appx. 200m north west of j/w Oaklawn Founction with Oaklawn Road	1	slight slight slight 2 serious
	Total 8	

A245 Randalls Road within Mole Valley District:

Location	Number of Collisions	<u>Severity</u>
Junction with Springfield Drive Junction with Crematorium access road Appx. 100m south of j/w River Lane	1 2 1	slight slight slight
	Total 4	

- 2.3 Many of the collisions involved single vehicles, though excessive speed was not a factor in any incident. Two collisions were as a result of travelling too fast for the prevailing conditions. It is likely that the nature of the road was contributory in most incidents, as there are many bends throughout.
- 2.4 One collision involving a pedestrian was recorded for the selected period. This took place south of the junction with River Lane.

2.5 A speed survey was undertaken on Woodlands Lane on 22 July 2009. The survey results showed that the mean speed for eastbound traffic was 40mph and for westbound traffic it was 41mph.

3 OPTIONS

- 3.1 Surrey County Council has a speed management policy for determining and applying speed limits on the public highway. This was updated in 2005 to reflect the changes arising from the Department of Transport's revised speed limit guidance. Assessed against these criteria the personal injury collision rate has been calculated as 70.
- 3.2 Tier 1 roads such as the A245 would have a preferred speed limit of 50 or 60 mph depending upon the rate of personal injury collisions per 100 million vehicle km. 50 mph for more than 35 and 60 mph for less than 35 personal injury collisions per 100 million vehicle km.
- 3.3 Tier 2 roads such as Oaklawn Road would have a preferred speed limit of 40 or 50 mph.
- 3.4 As this section of A245 has a collision rate of over 35 policy states that a speed limit of 50mph should be in force. As Oaklawn Road has a collision rate of 0 policy states that a speed limit of 50 mph should be in place.
- 3.5 However, Members are reminded about the changes to the Speed Limit Policy that now apply. These changes state that in exceptional circumstances the local committee may like to proceed with a change to a speed limit, against officer advice, in this instance the final decision would be taken by the Surrey County Council Cabinet Member for Transport. Speeds, the casualty record and safety concerns should be reviewed after 12 months and in the event of the new speed limit being ineffective, the policy recommends that remedial action be considered. This review may be needed earlier if there are extenuating circumstances that warrant prompt action
- 3.6 Speed limit repeater signs would be required to notify drivers and allow the lower limit to be enforceable.

4 CONSULTATIONS

4.1 Consultation has been carried out with Surrey Police and their view is that they would support a reduction to 40 mph, which is lower than the 50 mph speed limit that SCC Officers would recommend progressing.

5 FINANCIAL AND VALUE FOR MONEY IMPLICATIONS

5.1 The cost of making the Traffic Regulation Order and installation of the required signs will be in the region of £15,000.

5.2 These works would be funded centrally, by the Local Highway Services Group.

6 EQUALITIES AND DIVERSITY IMPLICATIONS

6.1 There are no Equality and Diversity implications at this time.

7 CRIME AND DISORDER IMPLICATIONS

7.1 There are no Crime and Disorder implications at this time.

8 CONCLUSION AND RECOMMENDATIONS

- 8.1 A reduction in limit to 40 mph does not comply with the policy, but would have the support of Surrey Police.
- 8.2 Surrey County Council Officers therefore recommended to reduce the maximum speed limit of the A245 Woodlands Road / A245 Randalls Road from its current national speed limit (60 mph) to 50 mph from the junction with Stoke Road / Cobham Road to the existing 30 mph termination point 200 metres south east of the access road to Leatherhead Crematorium.
- 8.3 It is also recommended that the existing signing be improved throughout the route, under current maintenance regimes, to improve safety.

9 REASONS FOR RECOMMENDATIONS

- 9.1 Provision of a reduction in signed speed limit from the existing national speed limit (60 mph) to 50mph along the section location stated would meet the County Council's speed limit policy in terms of the measured average speeds and greatly assist the Police in enforcement of the motorists who are speeding. The reduction in speed limit and additional signing should assist in reducing the personal injury collisions.
- 9.2 Changes to the Speed Limit Policy state that the local committee may like to proceed with a change to a speed limit, against officer advice. The final decision being taken by the Surrey County Council Cabinet Member for Transport.

10 WHAT HAPPENS NEXT

10.1 If the Local Committee approves this speed limit reduction, Surrey County Council's Legal Department will be asked to progress the Traffic Regulation Order. This will include a full, statutory consultation that involves Emergency Services.

- 10.2 If no objections are received when the Traffic Regulation Order is advertised the 50mph Speed limit Traffic Regulation Order will be made and the relevant signs erected on site.
- 10.3 A review of the existing signing along the routes will need to take place in order to confirm what improvements need to be made.

LEAD OFFICER: John Lawlor

TELEPHONE NUMBER: 03456 009 009

E-MAIL: highways@surreycc.gov.uk

CONTACT OFFICER: Philippa Gates

TELEPHONE NUMBER: 03456 009 009

E-MAIL: highways@surreycc.gov.uk

BACKGROUND PAPERS: None

APPENDIX 1

ANNEX 1

Location Plan A245 Woodlands Road /Randalls Road, D 131 Oaklawn Road – Speed Limit Assessment

