

Speed Management Plan

Printed: 24/05/12

*KSI - Killed & Seriously Injured PIC - Personal Injury Collision

85th Percentile Speed (mph) - the speed above which the fastest 15% of vehicles travel.

CRO - Casualty Reduction Officer, CSW - Community Speed Watch, NSO - Neighbourhood Specialist Officer, REED - Roadside Education Enforcement Day, RPCSO - Roads Police Community Support Officer, RPU - Roads Policing Unit, SCP - Safety Camera Partnership, SDR - Speed Detection Radar, SSW - School Speed Watch, VAS - Vehicle Activated Sign, VSL - Variable Speed Limit

Status	Road No.	Road Name	From	To	Length (m)	Collision Summary (2009-2011)				Speed Limit (mph)	Speed Survey Data			Existing or Proposed Highway Improvements	Police Enforcement Actions / proposals	Archive details
						Total KSI* (2009 - 2011)	Total PIC* (2009 - 2011)	Total KSI*/km	Total PIC*/km		Date of Survey	Mean Speed (mph)	85th Percentile Speed (mph)			
Live	A23	London Road North & South (Casualty Reduction Route)	Shepards Hill	Gatton Park, Redhill	2514	1	30	0.4	11.9	30	London Road North Jan 2011 (7-day, 24 hrs)	Nbnd 28.6, Sbnd 30.1	Nbnd 31.7, Sbnd 35.2	Existing VAS x 3	SCP - fixed safety camera, CRO, RPU and RPCSO enforcement, SSW, CSW	
Live	A23	Brighton Road, Horley (Casualty Reduction Route)	Chequers RAB	Borough Boundary (M V)	1682	3	31	1.8	18.4	30	May 2011 (7-day, 24 hrs)	Church Rd - Massetts Rd: Nbnd 33.4, Sbnd 26.6, Lumley Rd - Oakwood Rd: Nbnd 32.1, Sbnd 30.8	Church Rd - Massetts Rd: Nbnd 33.4, Sbnd 26.6 Lumley Rd - Oakwood Rd: Nbnd 37.2, Sbnd 37.5		CRO, RPU, RPSCO, patrol enforcement, SCP - Core mobile camera enforcement, REED	
Live	A23	Brighton Road, Salfords	Honeycrock Lane	Pear Tree Hill	1000	2	4	2.0	4.0	40	May 2011 (7-day, 24 hrs)	Nbnd 35.8, Sbnd 41.0	Nbnd 40.3, Sbnd 47.5		CRO and RPU enforcement, SCP - Core mobile camera enforcement, Operation site	
Live	A23	Horley Road/Brighton Road, Salford	Honeycrock Lane	Three Arch Road	1530	3	33	2.0	21.6	30 / 40		Speed survey to be undertaken	Speed survey to be undertaken	Existing VAS	CRO and RPU enforcement, Operation site	
Live	A23	Bonehurst Road, Horley	Cross Oak Lane	Pear Tree Hill (Fairlawn Business Park)	445	0	0	0.0	0.0	40		Speed survey to be undertaken	Speed survey to be undertaken		CRO and RPU enforcement, Operation site	
Live	A23	Bonehurst Road, Horley (Casualty Reduction Route)	Crossoak Lane	Balcombe Rd	1070	0	11	0.0	10.3	40		Speed survey to be undertaken	Speed survey to be undertaken	Proposal for new traffic signals	CRO and RPU enforcement, Operation site	
Live	A240	Reigate Road	A217 Brighton Road	Boundary	2685	6	31	2.2	11.5	30	S20/21 - June 2010, near ASDA Feb 2010 (7-day, 24 hrs)	S20/21 - Nbnd 35.1 Sbnd 36.6; near ASDA - Nbnd 27.9 Sbnd 25.6	S20/21 - Nbnd 40 Sbnd 42, near ASDA - Nbnd 33 Sbnd 30	Existing VAS, proposed safety engineering scheme near Yew Tree Bottom	SCP - bi-direction fixed safety camera and mobile enforcement, RPU enforcement, 3D signs	
Live	A217	Dovers Green Road / Reigate Road	Woodhatch Road	Borough boundary, Hookwood (M V)	4928	3	16	0.6	3.2	30 / 50	50 mph limit - Sept/Oct 2009 (7-day, 24 hrs) nr Hookwood	Nbnd 44, Sbnd 46	Nbnd 51, Sbnd 52	Existing VAS x 3	CRO and RPCSO enforcement	
Live	A217	Brighton Road	Winkworth Road	County Boundary (LB Sutton)	1392	1	9	0.7	6.5	60	April 2010 (7-day, 24 hrs)	Sbnd 51.4, Nbnd 47.7	Sbnd 59, Nbnd 57	Existing VAS x 2	RPU and patrol enforcement	
Live	A217	Brighton Road, Banstead	Garratts Lane	Fir Tree Road	1000	0	11	0.0	11.0	40	May 2010 (7-day, 24 hrs)	Nbnd 37.4 Sbnd 39.8	Nbnd 40.4, Sbnd 45.6	Existing VAS	SCP - Northbound Fixed camera and mobile enforcement, patrol enforcement	
Live	A217	Brighton Road, Lower Kingswood	Green Lane	Babylon Lane	1000	0	10	0.0	10.0	40	Sept 2011 (7-day, 24 hrs)	Nbnd 35.6, Sbnd 40.4	Nbnd 39, Sbnd 46	Existing VAS x 3	SCP - Bi directional fixed camera and patrol enforcement	
Live	A217	Brighton Road, Tadworth	Oatlands Road	Waterhouse Lane	810	0	7	0.0	8.6	40	May 2010 (7-day, 24 hrs)	Nbnd 39.6, Sbnd 35.9	Nbnd 44.5, Sbnd 40	Existing VAS	SCP - Bi directional fixed camera and patrol enforcement	
Live	A25	West Street, Reigate	High Street	32m west of western arm of Flanchford Road	865	3	9	3.5	10.4	30	18/11/2011 - 28/11/2011 (Police SDR survey)	Wbnd - 31, Ebnd 32	Wbnd - 35, Ebnd 38		CSW, CRO and RPCSO enforcement	
Live	B2221	Great Tattenhams, Banstead	A240 Reigate Road	Borough boundary (E & E)	1456	1	9	0.7	6.2	30	Nov 2011 (7-day, 24 hrs)	Nbnd 26.4, Sbnd 28.1	Nbnd 30, Sbnd 33		SCP - Existing bi-direction fixed safety camera, CSW, SSW	
Live	A217	Reigate Hill	Fox Lane	Conifer Close	1000	0	13	0.0	13.0	30	June 2010 (7-day, 24 hrs)	Nbnd 27.7, Sbnd 28.2	Nbnd 30.9, Sbnd 34.5		SCP - Southbound Fixed camera enforcement	
Live	B2032	Dorking Road, Walton Heath	Little Heath	Walton Heath Sports Club	1000	0	5	0.0	5.0	40	17/01/2012 - 24/01/2012 (Police SDR survey)	Wbnd - 39, Ebnd 35	Wbnd - 43, Ebnd 39		SCP - Northbound Fixed camera and mobile enforcement	
Live	B2032	Outwood Lane, Kingswood	Rectory Lane	Waterhouse Lane	4050	2	10	0.5	2.5	30/40		Speed survey to be undertaken	Speed survey to be undertaken		Monitor	
Live	B2036	Balcombe Road, Horley	Smallfield Road	35m of access to Coppingham Arms PH car park	1552	3	9	1.9	5.8	30 / 40		Speed survey to be undertaken	Speed survey to be undertaken	Existing VAS	Monitor	
Live	B248	Yew Tree Bottom Road	Reigate Road	Borough Boundary (E & E)	696	0	2	0.0	2.9	30	Sept/Oct 2011 (Police SDR survey)	Ebnd 36, Wbnd 40	Ebnd 42, Wbnd 46	Existing VAS	SCP - exceptional mobile enforcement, CRO enforcement, CSW	
Live	C134	Park Road, Banstead	Woodmansterne Lane	B2032 Outwood Lane	2285	1	4	0.4	1.8	30 / 60		Speed survey to be undertaken	Speed survey to be undertaken		CSW	
Live	C224	Linkfield Lane, Redhill	London Road	Station Road	1065	1	10	0.9	9.4	30	03/05/2012 - 10/05/2012 (Police SDR survey)	Ebnd - 29, Wbnd 28	Ebnd - 35, Wbnd 35		Monitor	
Live	C58	Flanchford Road, Reigate	A25, West Street	Borough Boundary (M V)	3277	0	2	0.0	0.6	30 / 40	15/02/2012 - 22/02/2012 (Police SDR survey)	Wbnd - 29, Ebnd 28	Wbnd - 35, Ebnd 34		CSW	

*KSI - Killed & Seriously Injured PIC -
Personal Injury Collision85th Percentile Speed (mph) - the speed above which
the fastest 15% of vehicles travel.CRO - Casualty Reduction Officer, CSW - Community Speed Watch, NSO - Neighbourhood
Specialist Officer, REED - Roadside Education Enforcement Day, RPCSO - Roads Police
Community Support Officer, RPU - Roads Policing Unit, SCP - Safety Camera Partnership, SDR -
Speed Detection Radar, SSW - School Speed Watch, VAS - Vehicle Activated Sign, VSL - Variable
Speed Limit

Status	Road No.	Road Name	From	To	Length (m)	Collision Summary (2009-2011)				Speed Limit (mph)	Speed Survey Data			Existing or Proposed Highway Improvements	Police Enforcement Actions / proposals	Archive details
						Total KSI* (2009 - 2011)	Total PIC* (2009 - 2011)	Total KSI*/km	Total PIC*/km		Date of Survey	Mean Speed (mph)	85th Percentile Speed (mph)			
Live	C65	Honeycrock Lane / Axes Lane, Salfords	A23, Brighton Road	41m east of jct Picketts Lane / Bridge Road	1059	1	9	0.9	8.5	30	Feb 2009 (7-day, 24 hrs)	Wbnd 30, Ebnd 29	Wbnd 34, Ebnd 32		Monitor	
Live	C67	Nutfield Road, South Merstham	Orpin Road	Mill Lane	365	0	0	0.0	0.0		15/02/2012 - 22/02/2012 (Police SDR survey)	Ebnd - 30, Wbnd 31	Ebnd - 35, Wbnd 35		Site to be reviewed	
Live	D1206	St Albans Road	Brokes Road	Somers Road	350	0	0	0.0	0.0			Speed survey to be undertaken	Speed survey to be undertaken		Monitor	
Live	D1210	Raglan Road	Reigate Hill	Croydon Road	1145	0	0	0.0	0.0	30	12/03/2012 - 18/03/2012 (Police SDR survey)	Wbnd - 22, Ebnd 26	Wbnd - 27, Ebnd 30	traffic calmed (speed humps)	Monitor	
Archive	A2022	Winkworth Road, Banstead	A217 Brighton Road	Sutton Lane	1058	1	11	0.9	10.4	40		Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	Feb 2012 - Speed issue not identified, no resident complaints within last 12 months.
Archive	A242	Gatton Park Road	Colesmead Road	A23 London Road	565	0	1	0.0	1.8	30		Speed survey to be undertaken	Speed survey to be undertaken	Existing toucan crossing near Monson Road installed Aug 2011	Site to be reviewed	Feb 2012 - Speed issue not identified, no resident complaints within last 12 months.
Archive	B2219	Holly Lane, Banstead	Garratts Lane	5m south of Holly Lane West	834	0	2	0.0	2.4	20 / 30		Speed survey to be undertaken	Speed survey to be undertaken	Existing VAS	Site to be reviewed	May 2011 - Speed issue not identified, no resident complaints within last 12 months.
Archive	C226	Pendleton Road, Redhill	St John's School	55m south of Abinger Drive	685	0	3	0.0	4.4	20 VSL 30		Speed survey to be undertaken	Speed survey to be undertaken	Existing VAS	Site to be reviewed	Feb 2012 - Speed issue not identified, no resident complaints within last 12 months.
Archive	C66	Smallfield Road, Horley	Balcombe Road	46m east of Langshott	1208	0	4	0.0	3.3	30		Speed survey to be undertaken	Speed survey to be undertaken		Monitor	Feb 2012 - Speed issue not identified, no resident complaints within last 12 months.
Archive	D1000	Ruden Way	Reigate Road	Fir Tree Road	1106	0	0	0.0	0.0	30		Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	May 2011 - Speed issue not identified, no resident complaints within last 12 months. Parking issues
Archive	D1071	Woodmansterne Lane	Park Road	Woodmansterne Street	1414	0	0	0.0	0.0	30		Speed survey to be undertaken	Speed survey to be undertaken	Road narrowing implemented in Woodmansterne Street Jan 2010	Site to be reviewed	Feb 2012 - Speed issue not identified, no resident complaints within last 12 months.
Archive	D332	Ironsbottom, Sidlow	Reigate Road	Collendean	3286	0	2	0.0	0.6	30 / 40		Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	May 2011 - Speed issue not identified, no resident complaints within last 12 months.
SPARE						0	0	#DIV/0!				Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	
0	A242	Croydon Road, Reigate	Reigate Road	Batts Hill	1180	2	11	1.7	9.3	30	03/05/2012 - 10/05/2012 (Police SDR survey)	Sbnd - 32, Nbnd 35	Sbnd - 38, Nbnd 40		Site to be reviewed	
0	D1182	Wray Lane, Reigate	Reigate Hill	Gatton Park Road	1400	0	1	0.0	0.7	30		Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	