

FLOODING & DRAINAGE SCHEMES 2008/09 IN TANDRIDGE

PROJECT	FUNDING	VALUE	COMMENTS
Stanstead Road, Caterham	LTP	50,000	Existing soakaway not working. Alternative solutions being investigated.
Bletchingley Road, Godstone	LTP	40,000	Existing outfall pipe in poor condition to be replaced.
Racecourse Road, Dormansland	LTP	65,000	Flooding caused by insufficient drainage. Improvements to be investigated.