

Speed Management Plan for Woking

Printed: 08/03/12

*KSI - Killed & Seriously Injured PIC - Personal Injury Collision

85th Percentile Speed (mph) - the speed above which the fastest 15% of vehicles travel.

CRO - Casualty Reduction Officer, CSW - Community Speed Watch, NSO - Neighbourhood Specialist Officer, REED - Roadside Education Enforcement Day, RPCSO - Roads Police Community Support Officer, RPU - Roads Policing Unit, SCP - Safety Camera Partnership, SDR - Speed Detection Radar, SSW - School Speed Watch, VAS - Vehicle Activated Sign, VSL - Variable Speed Limit

Status	Road No.	Road Name	From	To	Length (m)	Collision Summary (2008-2010)				Speed Limit (mph)	Speed Survey Data			Existing or Proposed Highway Improvements	Police Enforcement Actions / proposals	Archive details
						Total KSI* (2008 - 2010)	Total PIC* (2008 - 2010)	Total KSI/km	Total PIC/km		Date of Survey	Mean Speed (mph)	85th Percentile Speed (mph)			
Live	A245	Parvis Road (Casualty Reduction Route)	Borough Boundary	Eastside of M25 over bridge	1440	3	25	2.1	17.4	30		Speed survey to be undertaken	Speed survey to be undertaken	VAS x 2, speed limit reduced to 30 mph June 2011	Enforcement by CRO, RPU, RPCSO	
Live	A245	Old Woking Road (Casualty Reduction Route)	Sheerwater Road	Station Approach	560	1	16	1.8	28.6	30		Speed survey to be undertaken	Speed survey to be undertaken		Enforcement by CRO, RPU, RPCSO	
Live	A245	The Corner / Parvis Road (Casualty Reduction Route)	Station Approach	Eastside of M25 over bridge	1400	2	23	1.4	16.4	30 / 40		Speed survey to be undertaken	Speed survey to be undertaken		Enforcement by CRO, RPU, RPCSO	
Live	A320	Egley Rd, Woking	Almond Ave	Wych Hill Lane	815	4	11	4.9	13.5	40		Speed survey to be undertaken	Speed survey to be undertaken	Possible ITS scheme near Blackbridge Road	Site to be reviewed	
Live	A324	Hermitage Road, Brookwood	Elmgrove Close	Amstel Way	750	1	8	1.3	10.7	30	19/01/2011 (1 week survey)	wbnd - 25, ebnd - 24.6	wbnd - 29, ebnd - 27.7		SCP - fixed speed camera, SSW, Drive SMART op	
Live	B382	Old Woking Road (Casualty Reduction Route)	East Hill	Sheerwater Road roundabout	2120	0	13	0.0	6.1	40	7/05/2009 (1-week survey)	Nbnd - 39.6, Sbnd - 39.4	Nbnd - 45, Sbnd - 44		Enforcement by CRO, RPU, RPCSO, temp. VAS site	
Live	C144	Monument Road / Maybury Hill	Old Woking Road	South of Canal Bridge	1450	1	22	0.7	15.2	30		Speed survey to be undertaken	Speed survey to be undertaken	VAS x 2	Enforcement by CRO and RPCSO, Drive SMART op	
Live	D3668	Albert Drive, Sheerwater (Casualty Reduction Route)	Sheerwater Road	Blackmore Crescent	2010	2	14	1.0	7.0	30		Speed survey to be undertaken	Speed survey to be undertaken	VAS x 4	Enforcement by RPU, CRO and RPCSO, SSW Drive SMART op	
Live	D3668	Albert Drive, Sheerwater (Casualty Reduction Route)	Arnold Road	Blackmore Crescent	360	0	4	0.0	11.1	30		Speed survey to be undertaken	Speed survey to be undertaken	VAS x 2	Enforcement by RPU, CRO and RPCSO, SSW Drive SMART op	
Live	A245	Woodham Lane	Monument Road / Six Crossroads roundabout	Sheerwater Road	1930	3	14	1.6	7.3	40		Speed survey to be undertaken	Speed survey to be undertaken	VAS x 3	Enforcement by RPCSO	
Live	A320	Egley Road	Mayford Green	Almond Avenue	850	1	8	1.2	9.4	40	22/11/2009 (1 week survey)	Nbnd - 35.5, Sbnd - 35.8	Nbnd - 40, Sbnd - 40	VAS x 2	Enforcement by CRO	
Live	A322	Bagshot Road	Brookwood Lye Road	District Boundary	1230	1	11	0.8	8.9	30	10/08/09	38.1	42.9		Enforcement by CRO and RPCSO	
Live	B382	Old Woking Road	Maybury Hill	East Hill	810	1	6	1.2	7.4	40	07/05/2009 (1 week survey)	NEbnd - 39.6, SWbnd - 39.4	nebnd - 45, swbnd - 44	Proposed VAS	Enforcement by CRO and RPCSO, temp. VAS site	
Live	C143	Maybury Road	Monument Road	Stanley Road	930	0	11	0.0	11.8	30		Speed survey to be undertaken	Speed survey to be undertaken		Enforcement by CRO and RPCSO	
Live	D3731	East Hill	Sandy Lane	Old Woking Road	540	1	4	1.9	7.4	30		Speed survey to be undertaken	Speed survey to be undertaken		Enforcement by CRO, RPU, RPCSO	
Live	D3731	College Road, Woking	East Hill	Maybury Hill	265	0	5	0.0	18.9	30		Speed survey to be undertaken	Speed survey to be undertaken		Enforcement by CRO and RPCSO	
Live	A3046	Kettlewell Hill	Shores Road	Horsell Rise	810	0	3	0.0	3.7	30		Speed survey to be undertaken	Speed survey to be undertaken		Temp VAS site	

*KSI - Killed & Seriously Injured PIC - Personal Injury Collision

85th Percentile Speed (mph) - the speed above which the fastest 15% of vehicles travel.

CRO - Casualty Reduction Officer, CSW - Community Speed Watch, NSO - Neighbourhood Specialist Officer, REED - Roadside Education Enforcement Day, RPCSO - Roads Police Community Support Officer, RPU - Roads Policing Unit, SCP - Safety Camera Partnership, SDR - Speed Detection Radar, SSW - School Speed Watch, VAS - Vehicle Activated Sign, VSL - Variable Speed Limit

Status	Road No.	Road Name	From	To	Length (m)	Collision Summary (2008-2010)				Speed Limit (mph)	Speed Survey Data			Existing or Proposed Highway Improvements	Police Enforcement Actions / proposals	Archive details
						Total KSI* (2008 - 2010)	Total PIC* (2008 - 2010)	Total KSI/km	Total PIC/km		Date of Survey	Mean Speed (mph)	85th Percentile Speed (mph)			
Live	A3046	Chobham Road, Horsell	Horsell Rise	Victoria Way	530	1	6	1.9	11.3			Speed survey to be undertaken	Speed survey to be undertaken		Monitor	
Live	B367	Coldharbour Road	Upshott Lane	Hazel Road	1050	0	7	0.0	6.7	30		Speed survey to be undertaken	Speed survey to be undertaken	VAS x 2	Enforcement by SSW, CSW, RPCSO, CRO	
Live	B380	Westfield Road	New Lane	Granville Road	860	0	4	0.0	4.7	30	05/01/09	29.9	34.9	Pedestrian crossings, VAS x 2	CSW	
Live	B380	Smart's Heath Road / Mayford Green	Egley Road	Goose Lane	980	0	4	0.0	4.1	30 / 40		Speed survey to be undertaken	Speed survey to be undertaken	Virtual traffic calming, VAS	CSW	
Live	C140	Brewery Road	Chobham Road	Arthur's Bridge Road	920	1	2	1.1	2.2	30	21/03/09	34.1	39.8	VAS, signing, marker posts	Enforcement by CRO and RPCSO, CSW	
Live	C140	High Street / Church Hill, Horsell	South Road	Waldens Park Road	800	1	4	1.3	5.0	30		Speed survey to be undertaken	Speed survey to be undertaken		Monitor	
Live	C141	St Johns Hill Road / Hook Heath Avenue / Wych Hill	Railway Bridge	Orchard Mains	630	0	4	0.0	6.3	30	23/04/09	27.1	32.3		Enforcement by CRO, CSW and RPCSO	
Live	D3601	Ferndale Road, Horsell	Chobham Road	The Grove	310	0	0	0.0	0.0			Speed survey to be undertaken	Speed survey to be undertaken		Monitor	
Live	D3657	Woodham Road	Six Cross Roads	Grange Road	1040	0	3	0.0	2.9	30 / 50	17/02/2012 - 22/02/2012 (Police SDR survey)	Ebnd - 30, Wbnd - 29	Ebnd - 35, Wbnd - 34		Monitor	
Live	D3661	The Grove, Horsell	Chobham Road	Ferndale Road	280	0	0	0.0	0.0			Speed survey to be undertaken	Speed survey to be undertaken		Monitor	
Live	D3680	Saunders Lane	Smart's Heath Road	Hook Heath Road	1780	0	0	0.0	0.0	30		Speed survey to be undertaken	Speed survey to be undertaken		Enforcement by CRO and RPCSO, CSW	
Live	D3685	Prey Heath Road, Worplesdon	Burdenshott Road	Guildford Road	1015	0	2	0.0	2.0	30		Speed survey to be undertaken	Speed survey to be undertaken		Monitor	
Live	D3699	Westfield Avenue	Bonsey Lane	Kingfield Road	790	0	2	0.0	2.5	30		Speed survey to be undertaken	Speed survey to be undertaken		Monitor	
Live	D3710	Oriental Road	Maybury Hill	Heathside Crescent	1060	0	2	0.0	1.9	30		Speed survey to be undertaken	Speed survey to be undertaken		SSW	
Live	D3710	Park Road, Maybury	Pembroke Road	Maybury Hill	705	0	0	0.0	0.0	30	24/02/2012 - 01/03/2012 (Police SDR survey)	Wbnd - 27, Ebnd - 26	Wbnd - 32, Ebnd - 32		CSW	
Live	D7244	Goldsworth Road	Kingsway	Parley Drive	750	1	4	1.3	5.3	30		Speed survey to be undertaken	Speed survey to be undertaken		Enforcement by CRO and RPCSO	
Live	D7309	St John's Road	Trigg's Lane	Martin Way	1180	0	1	0.0	0.8	30	24/02/2012 - 3/03/2012 (Police SDR survey)	Wbnd - 41, Ebnd - 42	Wbnd - 48, Wbnd - 48		Enforcement by CRO and RPCSO	
Live	D7321	Redding Way	Bagshot Road	Lower Guildford Road	1860	3	5	1.6	2.7	30	17/02/2012 - 24/02/2012 (Police SDR survey)	Ebnd - 36, Wbnd - 39	Ebnd - 43, Wbnd - 42	VAS x 2	Enforcement by CRO and RPCSO	

*KSI - Killed & Seriously Injured PIC - Personal Injury Collision

85th Percentile Speed (mph) - the speed above which the fastest 15% of vehicles travel.

CRO - Casualty Reduction Officer, CSW - Community Speed Watch, NSO - Neighbourhood Specialist Officer, REED - Roadside Education Enforcement Day, RPCSO - Roads Police Community Support Officer, RPU - Roads Policing Unit, SCP - Safety Camera Partnership, SDR - Speed Detection Radar, SSW - School Speed Watch, VAS - Vehicle Activated Sign, VSL - Variable Speed Limit

Status	Road No.	Road Name	From	To	Length (m)	Collision Summary (2008-2010)				Speed Limit (mph)	Speed Survey Data			Existing or Proposed Highway Improvements	Police Enforcement Actions / proposals	Archive details
						Total KSI* (2008 - 2010)	Total PIC* (2008 - 2010)	Total KSI/km	Total PIC/km		Date of Survey	Mean Speed (mph)	85th Percentile Speed (mph)			
Archive	A320	Chertsey Road	Canal Bridge	Woodham Road	970	1	4	1.0	4.1	50		Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	Jan 2011 - Speed issue not identified, no resident complaints within last 12 months.
Archive	A324	Brookwood Lye Road	Blackhorse Road	Connaught Road	870	1	10	1.1	11.5	40 / 60		Speed survey to be undertaken	Speed survey to be undertaken	VAS x 1	Site to be reviewed	Feb 2012 - Speed issue not identified, no resident complaints within last 12 months.
Archive	A324	Hermitage Road, Brookwood	Elmgrove Close	Blackhorse Road	660	0	4	0.0	6.1	40		Speed survey to be undertaken	Speed survey to be undertaken	VAS x 1	Site to be reviewed	Feb 2012 - Speed issue not identified, no resident complaints within last 12 months.
Archive	A324	Amstel Way, Woking	Hermitage Road	Lockfield Drive	455	0	7	0.0	15.4	30		Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	Feb 2012 - Speed issue not identified, no resident complaints within last 12 months.
Archive	A324	Connaught Road	Brookwood Lye Road	Borough Boundary	1490	0	0	0.0	0.0	30		Speed survey to be undertaken	Speed survey to be undertaken	Traffic calmed	Site to be reviewed	May 2011 - Speed issue not identified, no resident complaints within last 12 months.
Archive	A324	Lockfield Drive	Parley Drive	Littlewick Road	2510	0	13	0.0	5.2	50 / 30		Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	Jan 2011 - Speed issue not identified, no resident complaints within last 12 months.
Archive	B382	Old Woking Road	Carters Lane	White Rose Lane	760	1	2	1.3	2.6	30		Speed survey to be undertaken	Speed survey to be undertaken	Proposed VAS	Site to be reviewed	Jan 2011 - Speed issue not identified, no resident complaints within last 12 months.
Archive	C11	Chobham Road	Limecroft Road	Barr's Lane	1110	1	6	0.9	5.4	30 / 40		Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	Feb 2012 - Speed issue not identified, no resident complaints within last 12 months.
Archive	C11	Chobham Road, Knaphill	Bagshot Road	Limecroft Road	460	0	3	0.0	6.5	30		Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	Jan 2011 - Speed issue not identified, no resident complaints within last 12 months.
Archive	C12	High Street, Knaphill	Chobham Road	Highclere Road	410	0	2	0.0	4.9	30		Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	Jan 2011 - Speed issue not identified, no resident complaints within last 12 months.
Archive	C142	Parley Drive	Triggs Lane	Lockfield Drive	550	0	4	0.0	7.3	40		Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	May 2011 - Speed issue not identified, no resident complaints within last 12 months.
Archive	C143	Walton Road	Stanley Road	Monument Road	950	1	7	1.1	7.4	30		Speed survey to be undertaken	Speed survey to be undertaken	Traffic calmed	Site to be reviewed	May 2011 - Speed issue not identified, no resident complaints within last 12 months.
Archive	D3603	Broadway	Bagshot Road	High Street	890	0	3	0.0	3.4	30		Speed survey to be undertaken	Speed survey to be undertaken		Monitor	Feb 2012 - Speed issue not identified, no resident complaints within last 12 months.
Archive	D3611 D3614	Gorsewood Road /Copley Close / Amis Road	Hermitage Road	Hermitage Road	1040	0	4	0.0	3.8	30		Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	May 2011 - Speed issue not identified, no resident complaints within last 12 months.
Archive	D3627	Beechwood Road	Barnby Road	Victoria Road	390	0	1	0.0	2.6	30		Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	May 2011 - Speed issue not identified, no resident complaints within last 12 months.
Archive	D3629	Sythwood	Tracious Close	Tresillian Way	568	0	3	0.0	5.3	30		Speed survey to be undertaken	Speed survey to be undertaken	VAS	Monitor	
Archive	D3679	Claremont Road, West Byfleet	Station Road	Camphill Road	455	0	0	0.0	0.0	30		Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	Feb 2012 - Speed issue not identified, no resident complaints within last 12 months.

*KSI - Killed & Seriously Injured PIC - Personal Injury Collision

85th Percentile Speed (mph) - the speed above which the fastest 15% of vehicles travel.

CRO - Casualty Reduction Officer, CSW - Community Speed Watch, NSO - Neighbourhood Specialist Officer, REED - Roadside Education Enforcement Day, RPCSO - Roads Police Community Support Officer, RPU - Roads Policing Unit, SCP - Safety Camera Partnership, SDR - Speed Detection Radar, SSW - School Speed Watch, VAS - Vehicle Activated Sign, VSL - Variable Speed Limit

Status	Road No.	Road Name	From	To	Length (m)	Collision Summary (2008-2010)				Speed Limit (mph)	Speed Survey Data			Existing or Proposed Highway Improvements	Police Enforcement Actions / proposals	Archive details
						Total KSI* (2008 - 2010)	Total PIC* (2008 - 2010)	Total KSI*/km	Total PIC*/km		Date of Survey	Mean Speed (mph)	85th Percentile Speed (mph)			
Archive	D3689	Mount Herman Road	Wych Hill Lane	Guildford Road	820	0	0	0.0	0.0	30		Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	Jan 2011 - Speed issue not identified, no resident complaints within last 12 months.
Archive	D3691	Brooklyn Road	Mount Herm Road	Guildford Road	340	0	0	0.0	0.0	30		Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	Jan 2011 - Speed issue not identified, no resident complaints within last 12 months.
Archive	D3706	New Lane	Sutton Green Road	Westfield Road	1850	0	1	0.0	0.5	40		Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	May 2011 - Speed issue not identified, no resident complaints within last 12 months.
Archive	D3765	St Mary's C of E School area			1180	0	0	0.0	0.0	30		Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	Jan 2011 - Speed issue not identified, no resident complaints within last 12 months.
Archive	D7206	Kirkland Avenue	Langmans Way	Clifton Way	780	0	0	0.0	0.0	30		Speed survey to be undertaken	Speed survey to be undertaken		Site to be reviewed	Jan 2011 - Speed issue not identified, no resident complaints within last 12 months.