

Reigate & Banstead Gully Cleaning Analysis 2009-10

	Wray Common	Reigate	Lower Kingswood	Tadworth	Tattenham	Nork	Banstead Downs	Chipstead Bottom	Merstham	Redhill	A217	A23	Earlswood	Petridge Wood	Salfords	Horley	Dovers Green	Meadvale	Totals
Programmed Gullies	906	1105	213	1330	1273	668	1023	556	949	1347	644	443	411	557	250	3126	862	914	16577
Gullies Cleaned	634	839	171	1224	1088	595	914	509	806	1135	0	0	0	0	0	0	0	0	7915
Parked Cars	139	124	5	72	114	32	78	30	118	84	0	0	0	0	0	0	0	0	796
Obstructed Gullies	4	25	2	5	7	6	0	2	2	13	0	0	0	0	0	0	0	0	66
Jammed Grids	55	75	3	39	36	22	29	19	25	71	0	0	0	0	0	0	0	0	374
Not Found	90	123	34	39	64	20	33	35	36	111	0	0	0	0	0	0	0	0	585
Blocked Outlets	6	9	2	15	24	29	26	10	19	20	0	0	0	0	0	0	0	0	160
Total Gullies Accounted For	922	1186	215	1379	1309	675	1054	595	987	1414	0	0	0	0	0	0	0	0	9736
% Accounted For Against Programmed	102%	107%	101%	104%	103%	101%	103%	107%	104%	105%	0%	0%	0%	0%	0%	0%	0%	0%	59%
% Cleaned Against Programmed	70%	76%	80%	92%	85%	89%	89%	92%	85%	84%	0%	0%	0%	0%	0%	0%	0%	0%	48%

