

Albury Road, Merstham bus stop (S'bound)


Current situation

Bus stopping area (bus stop is just beyond hedge in front of blue car on LHS of carriageway) is currently obstructed by parked cars meaning that bus passengers are unable to have step-free access onto/off the bus due to the bus having to stop in the road next to the parked cars, or only being able to pull into the stop at an angle just beyond any parked cars. This not only is an issue with regards to accessibility it also has repercussions on reliability of buses as they are having to negotiate the parked cars rather than being able to easily pull in & out of the kerb at the bus stop.





Location



Design Solution

This incorporates a small bus boarder which still allows for parking in the area but provides an area for the buses to align parallel to the kerb allowing bus passengers level access onto the bus. This solution will provide a better bus facility for passengers as well as improving reliability for bus services by buses not having to negotiate parked cars whilst only slightly reducing the parking in the locality.

