




Annex A – Gully Defect Report Examples

Drainage Investigation/Emergency Report		 great people : great work
Client's Name <u>May Gurne</u>	Conway House, Rochester Way, Dartford, Kent, DAI 3QY Tel: 020 8636 8822 Fax: 020 8636 8827	
Address/Area <u>Cobham</u>	Job No. _____ Chargeable Hours _____	
Postcode _____	47304	
Drivers Name <u>S. Osborne</u> Date <u>24/2/14</u>		
Operators Name <u>N. James</u> Reg. No. <u>DkroBDKx</u>		
Vehicle Type <u>Jim 1</u>		
Site Address <u>Old Common Road, Cobham</u>		
Comments/Remarks/Site Location <u>Settled kerb inlet GZ512. Defect in pipe unable to</u> <u>clear Blockage site left safe.</u>		
Site Diagram 		
Inspector's signature _____		Name _____ Please Print
Directors: M.J. Conway, K. Conway, S.A. Geraghty, N.H.J. Leaver Registered Office: 13 Station Road, Finchley, London N3 2SB Registered in England No: 706445		
		 Certification No. FM 33025

Drainage Investigation/Emergency Report



Client's Name KIER M/G

Address/Area _____

Postcode _____

Drivers Name S GATES Date _____

Operators Name B OGDEN Reg. No. _____

Vehicle Type SINI

Site Address DOWNSIDE RD TO BRIDGE
OVER RIVER MOLE


Job No. _____ Chargeable Hours _____

Conway House, Rochester Way,
Dartford, Kent, DA1 3QY
Tel: 020 8636 8822
Fax: 020 8636 8827

42626

Comments/Remarks/Site Location

CLEANED GULLYS BACK FILLING
MAIN LINE FULL DUE TO DITCH BEING VERY OVER
GROWN AND SILTED NEEDS DIGGING.
FURTHER WORK REQUIRED



Inspector's signature _____ Name _____
Please Print

Directors: M.J. Conway, K. Conway, S.A. Geraghty, N.H.J. Leaver
Registered Office: 13 Station Road, Finchley, London N3 2SB
Registered in England No: 706445



Certification No. FM 33025

Drainage Investigation/Emergency Report



Client's Name Luver m/g

Address/Area _____

Postcode _____

Drivers Name S Gden Date 17/3/14

Operators Name Brian Reg. No. RA52BAU

Vehicle Type 3 in 1

Site Address 7 MAYFIELD rd
Weybridge

Job No. _____ Chargeable Hours _____


Conway House, Rochester Way,
Dartford, Kent, DA1 3QY
Tel: 020 8636 8822
Fax: 020 8636 8827

47028

Comments/Remarks/Site Location

cleaned out Sully and Jcted to main line
running off

Site Diagram



Inspector's signature _____ Name _____
Please Print

Directors: M.J. Conway, K. Conway, S.A. Geraghty, N.H.J. Leaver
Registered Office: 13 Station Road, Finchley London N3 2SB
Registered in England No: 706445



Certification No. FM 33025

Drainage Investigation/Emergency Report




Client's Name Kier m/g.
Address/Area _____
Postcode _____
Drivers Name Sgdias Date 17/3/14
Operators Name Brian Reg. No. R457DAU
Vehicle Type Bin
Site Address Hurst Lane SG
East Molesey
Job No. _____ Chargeable Hours _____

Conway House, Rochester Way,
Dartford, Kent, DA1 3QY
Tel: 020 8636 8822
Fax: 020 8636 8827

42649

Comments/Remarks/Site Location

clean out gully and jets
Broken outlet
at side SG.



Inspector's signature _____ Name _____
Please Print

Directors: M.J. Conway, K. Conway, S.A. Geraghty, N.H.J. Leaver
Registered Office: 13 Station Road, Finchley, London N3 2SB
Registered in England No: 706445



Certification No. FM 33025